

# Certificate of Accreditation



## **NQA Certification Ltd**

Inspection Body No. 0356

**is accredited as a Type A body in accordance with International Standard ISO/IEC 17020:2012 - Conformity assessment – Requirements for the operation of various types of bodies performing inspection**

This accreditation demonstrates technical competence for a defined scope specified in the schedule to this certificate, and the operation of a management system (refer joint ISO-ILAC-IAF Communiqué dated September 2013). The schedule to this certificate is an essential accreditation document and from time to time may be revised and reissued.

The most recent issue of the schedule of accreditation, which bears the same accreditation number as this certificate, is available from [www.ukas.com](http://www.ukas.com).

This accreditation is subject to continuing conformity with United Kingdom Accreditation Service requirements.

A handwritten signature in black ink, appearing to read "Matt Gantley", is positioned above a horizontal line.

**Matt Gantley**, *Chief Executive Officer*  
United Kingdom Accreditation Service

Initial Accreditation: 27 July 2005  
Certificate Issued: 25 January 2021




Scan QR Code to  
verify

# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>0356</b> <b>Type A</b> <b>Inspection Body</b>  Accredited to ISO/IEC 17020:2012	<b>NQA Certification Ltd</b>	
	<b>Issue No: 012    Issue date: 21 January 2021</b>	
	<b>Head Office</b> <b>Warwick House</b> <b>Houghton Hall Park</b> <b>Houghton Regis</b> <b>Dunstable</b> <b>LU5 5ZX</b>	<b>Contact: Mr Steve Russell</b> <b>Tel: +44 (0)800 052 2424</b> <b>Email: info@nqa.com</b> <b>Website: www.nqa.com</b>
Inspection performed at/from the above address only		

### DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures
Recovery vehicles including associated equipment and processes, facilities and premises of Recovery & Breakdown Operators	In-service Inspection	PAS43:2015
END		